


Opaque Zeroing Cuvette

C100CS | Features and requirements to define



REFERENCE VALUES

The illustration identifies features; dimensions and mating details remain project requirements. Specify them on the drawing used for quotation and acceptance.

Illustrative design example; not an actual customer requirement.

Not to scale. Product-reference rendering with annotations; use the agreed drawing for dimensional acceptance.