

Three-Opening Quartz Screw-Top Cell

MQQSC048 | Features and requirements to define



1 Three access interfaces

Identify all three threaded access interfaces.

2 Accessory insertion angles

Check the approach angle of each proposed accessory.

3 Clear optical region

Keep the lower optical region clear.

REFERENCE VALUES

Nominal path

10 mm

Illustrative design example; not an actual customer requirement.

Not to scale. Product-reference rendering with annotations; use the agreed drawing for dimensional acceptance.